


CORNIER




| DIMENSIUNE mm | GREUTATE Kg/m |
|------------------|------------------|
| 20 x 20 x 3 | 0,88 |
| 25 x 25 x 3 | 1,12 |
| 30 x 30 x 3 | 1,36 |
| 30 x 30 x 4 | 1,78 |
| 35 x 35 x 4 | 2,10 |
| 40 x 40 x 4 | 2,42 |
| 40 x 40 x 5 | 2,97 |
| 50 x 50 x 5 | 3,77 |
| 60 x 60 x 6 | 5,42 |
| 80 x 80 x 8 | 9,66 |
| 100 x 100 x 10 | 15,00 |

TOLERANTE DIMENSIONALE

| Dim. Nominală a | a ≤ 50 | 50 < a ≤ 100 | 100 < a ≤ 150 | 150 < a ≤ 200 |
|------------------|--------|--------------|---------------|---------------|
| Tolerante ptr. a | ± 1 | ± 1,5 | ± 2 | ± 3 |
| Tolerante ptr. e | ± 0,5 | ± 0,75 | ± 1 | ± 1,2 |

„T“- uri



| DIMENSIUNE mm | GREUTATE Kg/m |
|------------------|------------------|
| 20 x 20 x 3 | 1,15 |
| 30 x 30 x 3 | 1,42 |
| 40 x 40 x 4 | 2,62 |
| 50 x 50 x 5 | 3,93 |

TOLERANTE DIMENSIONALE

| Dim. Nominale a | a ≤ 50 | 50 < a ≤ 100 |
|-------------------|--------|--------------|
| Tolerante pt. a b | ± 1 | ± 1,5 |
| Tolerante pt. e | ± 0,5 | ± 0,75 |